Series 800M4, LF800M4, 800M4FR, LF800M4FR

Pressure Vacuum Breaker

Sizes 1/2" - 2"

Repair Kits

When ordering specify Ordering Code, Kit No., and Valve Size.

ORDERING CODE	KIT NO.	SIZE	
Total Repa	ur Kits		
0887727	RK 800M4-T	1/2", 3/4"	
0887728	RK 800M4-T	1"	
0887729	RK 800M4-T	1 1/4" – 2"	
	CODE Total Repa 0887727 0887728	CODE Total Repair Kits 0887727 RK 800M4-T 0887728 RK 800M4-T	CODE Total Repair Kits 0887727 RK 800M4-T 1/2", 3/4" 0887728 RK 800M4-T 1"

Kit consists of: check valve repair kit, vent float repair kit, bonnet assembly repair kit, seat repair kit

Check Kits

۱ س	0887703	**RK 800M4 CK	1/2", 3/4"
Ë	0887704	**RK 800M4 CK	1"
LEA	0887705	**RK 800M4 CK	1 1/4" – 2"

Kit consists of: check disc assembly (disc & disc holder), bonnet 0-ring and check spring. **Fits 800M4FR models

Vent Float Kits

FREE'	0887709	RK 800M4 V	1/2", 3/4"	
A F	0887710	RK 800M4 V	1"	
LEA	0887711	RK 800M4 V	1 1/4" – 2"	

Kit consists of: float vent disc assembly (vent float, seal & spring) and bonnet O-ring.

FR Vent Float Kits

FRE	0887725	RK 800M4 FRV	1/2", 3/4"	
	0887715	RK 800M4 FRV	1"	
LEA	0887716	RK 800M4 FRV	1 1/4" – 2"	

Kit consists of: float disc assembly, vent spring and bonnet O-ring.

Retrofit Kits (Kits to convert 800M4QT to 800M4FR)

		•	
Ĩ	0887726	Retro 800M4 FR	1/2", 3/4"
	0887718	Retro 800M4 FR	1"
LEA	0887717	Retro 800M4 FR	1 1/4" – 2"

Kit consists of: float disc assembly, vent spring, bonnet, bonnet 0-ring. (1 1/4" - 2" Kit also includes hood & screws)

Bonnet Assembly Kits

FREE'	0887700	RK 800M4 B	1/2", 3/4"	
Å F	0887701	RK 800M4 B	1"	
LEA	0887702	RK 800M4 B	1 1/4" – 2"	

Kit consists of: bonnet, bonnet O-ring, vent spring, hood & hood screws.

Rubber Parts Kits

ين س	0887706	RK 800M4 RT	1/2", 3/4"	
Ë	0887707	RK 800M4 RT	1"	
LEA	0887708	RK 800M4 RT	1 1/4" – 2"	

Kit consists of: vent seal, check disc and bonnet O-ring.

Seat Kits

Ĩ	0887712	RK 800M4 S	1/2", 3/4"	
	0887713	RK 800M4 S	1"	
LEA	0887714	RK 800M4 S	1 1/4" – 2"	

Kit consists of: seat, seat O-ring and bonnet O-ring.







Inlet Shutoff valve

*The wetted surface of this product contacted by consumable water contains less than 0.25% of lead by weight.